



**ClearMax Plus™**  
**How To Guide**

**ClearMax Plus™** Multi-Temp Clearcoating System acts as a liquid clearcoat and is used to repair scratches, swirl marks, and faded panels permanently. **ClearMax Plus™** features a self-leveling agent to provide a smoothing effect on the panels it's applied to.

There are 2 types of **ClearMax Plus™**.

- **Cool-Temp** – Up to 50 degrees and up to 2 hours before precipitation.
  - **Cool-Temp** is for when the car is cool to lukewarm to the touch.
- **Hi-Temp** – Above 50 degrees and no precipitation forecasted for next 24 hours.
  - **Hi-Temp** is for when the temperature of the car is warm or hot to the touch.

*NOTE: Even when you are using the high heat version, if the vehicle is burning to the touch, you will need to move the car to the shade and allow it to cool before proceeding.*

---

**1) Clean It** – Before **ClearMax Plus™** application, you must clean any panels you're going to be clearcoating.

- a) Use **ClearMax Prep** to clean all vehicle panels you will be clearcoating..
- b) **Important:** – The surfaces must be clean for the product to work correctly.

---

**2) Mask It** – Mask off trim areas before **ClearMax Plus™** application.

- a) **Important:** – Use painter's tape to protect rubber trim areas and oxidized headlights.

---

**3) Apply It** – For **ClearMax Plus™** application, use a **BLUE** shop towel, folded 3 to 4 times.

- a) Saturate the entire towel with **ClearMax Plus™**, by saturate we mean “soaked” to the point where it's starting to drip from the rag.
- b) When in doubt, apply more, it's better to use too much than not enough.

---

**4) Wipe It** – Wipe **ClearMax Plus™** onto the vehicle, one panel at a time.

- a) Wipe on **ClearMax Plus™** starting at the top of the panel, working primarily in a horizontal pattern down the panel making sure to not miss any spots.
- b) Overlap pattern strokes slightly (i.e. mowing the yard.)

---

**5) Keep It Wet** – Add more **ClearMax Plus™** to towel as needed.

- a) If the blue shop towel gets dirty, rotate to a different spot or get a new blue shop towel.
- b) **Important:** Keep your **ClearMax Plus™** application clean.

---

**6) Reapply It** – *If necessary*, you can reapply **ClearMax Plus™** to areas where scratches reappear, up to a maximum of 3 times.

- a) Try to re-apply within 2 minutes from when it was first applied.
- b) **Important:** Do not apply another coat if it is tacky as this will make it streak.

---

Check out the **ClearMax Plus™** Tips & Troubleshooting guide on our website for more information.

**Website:** <https://www.finishfirstauto.com>